U.S. Department of Transportation

800 Independence Ave., S.W. Washington, D.C. 20591

Federal Aviation Administration

**Transmittal Letter 15-15** 

June 5, 2015

## PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, .....EFFECTIVE UPON PUBLICATION Identified as follows: **AIRAC** FDC FDC STATE **CITY** AIRPORT **SUBJECT** DATE **NUMBER** DATE RNAV (GPS) RWY 05/20/15 23-Jul-15 UT Vernal Vernal Rgnl 5/2584 34, Amdt 1B

FDC **5/2584** VEL IAP VERNAL RGNL, VERNAL, UT. RNAV (GPS) RWY 34, AMDT 1B... DELETE NOTE: WHEN VGSI INOP, STRAIGHT-IN AND CIRCLING RWY 34 PROCEDURE NA AT NIGHT. DELETE NOTE: WHEN VGSI INOP, CIRCLING RWY 7, 16, 25 NA AT NIGHT.. CHART NOTE: NIGHT LANDING: RWY 7 NA. DELETE NOTE: VISIBILITY REDUCTION BY HELICOPTERS NA. CHART NOTE: HELICOPTER VISIBILITY REDUCTION BELOW 3/4 SM NOT AUTHORIZED.

THIS IS RNAV (GPS) RWY 34, AMDT 1C. 1505151323-PERM